

Eco Green does the complete cleaning job by deeply penetrating baked on carbon, grease, oil, etc. by lifting them away from the hard surface and allowing them to be rinsed away freely with water. This product can be applied by pressure, steam and excels in both foam and general use applications.

ECO GREEN

Contains: Diethylene glycol monoethyl ether (CAS #111-90-0), Sodium dodecylbenzenesulfonate (CAS #25155-30-0)

WARNING

Causes skin irritation.
Causes eye irritation.

PRECAUTIONARY STATEMENTS

Prevention: Wash hands and exposed skin thoroughly after handling. Wear protective gloves. Response: IF ON SKIN: Wash with plenty water. Specific treatment (see Section 4 on the Safety Data Sheet) If skin irritation occurs: Get medical advice/attention. Take off contaminated clothing before reuse. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses if present and easy to do. Continue rinsing. If eye irritation persists: Get medical advice/attention.



Eco Green

All-Purpose Cleaner & Degreaser

Earth Friendly

1 Gallon
(128 FL. Oz.)

DIRECTIONS FOR USE

For washing trucks or automobiles **ECO GREEN** can be used by steam, pressure or bucket and brush.

IN OTHER AREAS: Dilute 1 part product with 15 to 20 parts of hot water. Apply by mop, spray or other suitable means, such as sponge or cloth. Allow Eco Green to penetrate soil. Then scrub with floor machine or manually with brush or sponge. Pick up foam. (On floors, use squeegee and wet dry vac, or mop foam into bucket of clear water. Excessive foam in the wet dry vac can be controlled by anti-foams.) Then, rinse with hot water spray.

IN FOOD APPLICATIONS: Cover or remove all food products from area. Remove gross soil from surfaces and equipment. Fill plastic bottle with Eco Green. Do not add any other product. Set foam sprayer to dilute 1:20-1:40. Apply hot foam liberally to all washable surfaces including floors, walls, tables, etc. Allow foam to cling to surface at least 5 minutes. Rinse. Use hot water with either high pressure sprayer or hose nozzle. Let surface drain dry. Do not wipe dry. Tilt movable surfaces to aid water run-off. To sanitize surfaces: Spray with PEPCOCIDE following directions on the container. Leave surfaces tilted until equipment is put back in use.

TO SOAK-CLEAN FILTERS, UTENSILS, EQUIPMENT: Dilute 1 part product with 15 to 20 parts hot water. Soak. Use brush or sponge as necessary. Rinse.

NOTE: Wear rubber or plastic gloves for manual cleaning. Metal surfaces should be rinsed immediately.